

## **!! URGENT !!**

Date: 9 February 2017 Subject: Leticia, Colombia Alfredo Vasquez Cobo (SKLT) Arrivals, Departures, & Approach Procedures

## As of 3 February 2017 Flight Information Incorrect

The following Jeppesen charts at Leticia, Colombia – Alfredo Vasquez Cobo (SKLT) depict incorrect flight information as of 3 February 2017. Colombia AIP Supplement C05/17 effective 3 February 2017 was received after the date specified by ICAO for aeronautical information distribution. As a result changes to the following charts could not be processed for the 3 February 2017 effective date.

The Aircraft Certification note has changed on: AROTI TWO CHARLIE & KALOR TWO ALFA Arrivals (10-2) dated 6 NOV 2015 (Eff 12 Nov). BUTAB ONE JULIET & SPRIN TWO ALFA Arrivals (10-2B) dated 6 NOV 2015 (Eff 12 Nov). MIKOX TWO ALFA & ROKUL TWO ALFA Arrivals (10-2C) dated 6 NOV 2015 (Eff 12 Nov). AROTI TWO DELTA, KALOR TWO BRAVO, MIKOX TWO BRAVO, & ROKUL TWO BRAVO Departures (10-3) dated 6 NOV 2015 (Eff 12 Nov). AROTI TWO ECHO, KALOR TWO DELTA, MIKOX TWO CHARLIE, & ROKUL TWO CHARLIE Departures (10-3A) dated 6 NOV 2015 (Eff 12 Nov). BUTAB ONE LIMA & SPRIN TWO CHARLIE Departures (10-3D) dated 6 NOV 2015 (Eff 12 Nov).

ILS Z Rwy 21 (11-1) dated 23 SEP 2016, Circling Restriction and Visibilities have changed. LOC Rwy 21 (11-2) dated 23 SEP 2016, Circling Restriction and Visibilities have changed. ILS Y Rwy 21 (11-3) dated 23 SEP 2016, Aircraft Certification, Circling Restriction, and Minimums. RNAV (GNSS) Rwy 21 (12-1) dated 23 SEP 2016, Aircraft Certification, Circling Restriction, and Minimums. VOR Y Rwy 03 (13-1) dated 23 SEP 2016, Holding, Circling Restriction, and Minimums. VOR Z Rwy 03 (13-2) dated 23 SEP 2016, Holding, Circling Restriction, MAP, and Minimums. VOR Rwy 21 (13-3) dated 23 SEP 2016, Circling Restriction and Visibilities.

Updated charts in PDF are attached for immediate use.

## THEREFORE, EXERCISE CAUTION WHEN ARRIVING AT OR DEPARTING FROM LETICIA, COLOMBIA – ALFREDO VASQUEZ COBO AIRPORT (SKLT)

These charts will be updated in the 24 FEB 2017 revision. This Chart Alert is also posted on the Jeppesen Web site at (<u>http://www.jeppesen.com/company/alerts/aviation-alerts.jsp</u>).

## WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS IMMEDIATELY!

If you have any questions concerning this Chart Alert, please contact Charting Technical Support at: U.S. Toll Free: 1-800-353-2107 Direct: 1-303-799-9090, Extension 5830

E-mail: ChartSupport@jeppesen.com

Chart Alerts (formerly ChartWatch Notices) are published to advise users of significant issues in Jeppesen chart data which may affect aircraft operations. These Alerts are distributed to affected chart users and are also available on Jeppesen's Web site at www.jeppesen.com.