



JEPPESEN.
NavData® Alert

!! URGENT !!

Date: 26 February 2010

Subject: Veracruz, Mexico
Gen Heriberto Jara Intl (MMVR)
VOR DME-2 Rwy 36 [D36]
Cycles 1002 & 1003

Incorrect Waypoint Placement

Jeppesen NavData for cycles 1002 and 1003, effective 11 February 2010 and 11 March 2010, respectively, contains an incorrect waypoint placement for D257J waypoint on the VOR DME-2 Rwy 36 [D36] TAMVO transition at Gen Heriberto Jara Intl, Veracruz, Mexico (MMVR).

THEREFORE, DO NOT USE VOR DME RWY 36 [D36] TAMVO TRANSITION AT MMVR IN CYCLES 1002 & 1003 NAVDATA.

Revised coding will appear in Jeppesen NavData for cycle 1004, effective 8 April 2010. Until then an entry will appear in the NavData Change Notices beginning 12 MAR 10, and this Alert will be posted on the Jeppesen Web site (<http://www.jeppesen.com/company/alerts/aviation-alerts.jsp?region=Latin%20America>). Please refer to the Veracruz, Mexico (MMVR) 13-9 chart dated 28 DEC 07 for valid information.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
Phone: 303-328-4445
E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.

MMVR 1002 & 1003