



JEPPESEN[®]
NavData[®] Alert

!! URGENT !!

Date: 15 April 2010

Subject: Vilnius, Lithuania
Vilnius Intl (EYVI)
RNAV SID TAGOL 1B [TAGO1B]
Cycle 1004

Incorrect RNAV Standard Instrument Departure Procedure Coding

Jeppesen NavData for cycle 1004, effective 08 April 2010, contains an incorrect RNAV procedure coding on the TAGOL 1B [TAGO1B] Standard Instrument Departure Procedure for Vilnius Intl Airport; Vilnius, Lithuania (EYVI).

THEREFORE, DO NOT USE THE TAGOL 1B [TAGO1B] STANDARD INSTRUMENT DEPARTURE PROCEDURE IN CYCLE 1004 NAVDATA.

Revised coding will appear in Jeppesen NavData for cycle 1005, effective 06 May 2010. Until then an entry will appear in the NavData Change Notices beginning 23 APR 2010, and this Alert will be posted on the Jeppesen Web site

(<http://www.jeppesen.com/company/alerts/aviation-alerts.jsp?region=Eastern%20Europe>) .

Please refer to the Vilnius, Lithuania (EYVI) 10-3L chart dated 26 MAR 10 (effective 08 April 2010) for valid information.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.